

**Parameters**

Emissivity	0.95
Refl. temp.	20 °C

Water at a basement wall. Very obvious in the Infrared image, this would probably be missed during a typical visual only inspection.

3/26/2014 6:21:40 PM



FLIR0119.jpg

FLIR E6

63911439

3/26/2014 6:21:40 PM



FLIR0119.jpg

FLIR E6

63911439