

Measurements °C


Sp1	2.9
Sp2	11.0

Parameters

Emissivity	0.95
Refl. temp.	20 °C

Further investigation of this area confirmed missing insulation. This made for a drafty bedroom.

2/8/2014 10:43:51 PM




FLIR0041.jpg

FLIR E6

63911439

2/8/2014 10:43:51 PM



FLIR0041.jpg

FLIR E6

63911439